## General Environmental Incident Summary

Incident: 3569 Date/Time Notice: 12/3/2014 DEM Incident No:

Responsible Party: Farstad Oil Inc.

Date Incident: 12/3/2014 Time Incident: 15:03 pm Duration: 2.5 minutes

County: Williams Twp: 154 Rng: 101 Sec: 2 Qtr:
Lat: 48.18324 Long: -103.62650 Method: Interpolation from map

Location Description: Racers 120

4201 2nd Ave West Williston ND 58801

Submitted By: Roger Bischof Affiliation:

Address: 100 27th St NE

City: Minot State: ND Zip:

Received By:
Contact Person:

100 27th St NE Minot, ND

Distance Nearest Occupied Building: 200 Feet Release Contained: Yes

Type of Incident: Tank Overflow

Description of Released Contaminant: Premium Nolead Gas

Volume Spilled: 108.00 gallons Aq Related: No

EPA Extremely Hazardous Substance: Unknown Reported to NRC: Unknown

Cause of Incident:

Driver was unloading into the tank and was just about done and it started to bubble out the vent when the truck was finished.

Risk Evaluation:

none

# of Fatalities: 0 # of Injuries: 0 Affected Medium: 09 - other

Potential Environmental Impacts:

There might be a liitle bit of gravel mixed with snow that is in the containment. There will be some floor mixed with product

Action Taken or Planned:

Called Scott Brown from Earthmovers and he called his staff in Williston to bring a vac truck over and pickup the gas. The gas was in the containment mixed with snow.

Wastes Disposal Location:

Agencies Involved:

Friday, January 27, 2017 Page 1 of 2

## **Updates**

Date: 12/3/2014 Status: Reviewed - Assigned to NDDoH Division Author: Roberts, Kris

**Updated Volume:** 

## Notes:

Overflow of gasoline inside tank containment structure at the Racers Truck Stop in Williston, just north of Walmart. This is an above-ground storage tank site with containment. Strata is responding. Appears there may be no impermeable liner under the storage tanks, but Strata is not sure at this point. Gasoline is mixed into ice and snow in the containment. They have dug down approximately 1 foot into the base. Gasoline appears to be seeping under one of the tanks. Vacuum truck has been on scene, and additional work is ongoing this date.

Friday, January 27, 2017 Page 2 of 2